


# StarGo board reverse motor cable connectors

- Unscrew the four screws



- Remove the StarGo Board

- Remove the RA/DEC motor cables



- Plug the RA/DEC motor cables connector in the reverse side

